

TENNESSEE DEPARTMENT OF ENVIRONMENT AND CONSERVATION

Division of Water Resources William R. Snodgrass Tennessee Tower, 312 Rosa L. Parks Avenue, 11th Floor, Nashville, Tennessee 37243 1-888-891-8332 (TDEC)

Tennessee Multi-Sector General NPDES Permit (TMSP) Compliance Inspection Report

Facility Name:	Harrison- April Rech, 1 1701 Santo Vace, Sweet.	M_{∞}	NPDES Tracking Number: TNE	1100			
Street Address:	Address: 1711 Santa Chara Supertulate County:			Monvae 16:50			
Facility SIC	Facility SIC Time of Entry:			16500			
Code(s): Sector(s): Time of Exit:					17:00		
Notice of Coverage (NOC) and Stormwater Pollution Prevention Plan (SWPPP)					No	N/A	
Is the facility's NOC retained on-site or available upon request?				Ø			
Has the facility developed and maintained a SWPPP?							
Does the SWPPP include: a detailed site map identifying drainage, outfalls, pollutant potential areas and BMPs							
an inventory of potential pollutant sources?							
a pollution prevention team?							
a list of measures and controls to prevent pollution?							
a description of good house keeping practices?							
	a list of erosion prevention and sediment co				Π,		
	a list of significant spills and leaks of toxic		ants?	<u> </u>			
a description of spill prevention and response procedures?							
a certification page signed by the appropriate authority?							
a description of employee training and dates delivered?				Q/			
	a certification of testing for presence of non-storm-water discharge?						
990.000.0000000000000000000000000000000	The state of the s			Yes	BSC	27/4	
Quarterly Visual Examination of Stormwater Quality				res	No 🗆	N/A	
Has the permittee performed quarterly visual examinations in accordance with the requirements of the TMSP?						<u> </u>	
Are the visual examination reports retained on-site or available upon request?							
Stormwater Monitoring					No	N/A	
Has the permittee performed stormwater monitoring at all of the outfalls?				<u>a</u>			
Have all of the required parameters been monitored?							
Have the samples been collected in accordance with the requirements of the TMSP and/or 40 CFR?							
Are the monitoring reports and associated documentation retained on-site or available upon request?							
Did the facility notify the Division within the required time frame if benchmark exceedances occurred?							
				Yes	No	N/A	
Comprehensive Site Compliance Evaluations and Inspections Les the permittee performed appropriate compliance evaluations?							
Has the permittee performed annual comprehensive site compliance evaluations? Has the permittee performed any required site inspections?							
Are the evaluations and inspection records retained on-site or available upon request?							
Are the evaluation	s and hispection records retained on-site of available	upon request:					
Facility BMP Review					No	N/A	
Are the site BMPs in accordance with the SWPPP?							
Have the BMPs been installed correctly and maintained?							
Have good housekeeping measures been implemented and maintained?							
Outfall and Receiving Waters (where applicable) Outfall #Outfall #							
Was an outfall discharging at time of inspection? If yes, explain							
	bservations (source/color/odor/foam/scum/solids etc.).						
	Condition of receiving water upstream from the outfall?						
Condition of receiv							
Condition of receive	ving water feet downstream of the outfall?						

Observations and Comments:					
	1				
	· · · · · · · · · · · · · · · · · · ·				
19.					
On-Site Contact Person:	DWR Inspector:				
Print Name:	Print Name: Allen Wilhing				
Title: Date:	Title: Date:				
Signature:	Signature: Sthe William				
Phone:	Phone: 815-594-13-88				
Email:	Email: allen, Wi est				
24/10/7001					